

## Firmware Update Information

### Firmware Change History

Version	Category	Detail	Effect
09.69.WO31PA	Security Bug Fix	Fixed an issue where the Epson Connect registration button would not respond when logged in to the control panel with a sub-administrator account.	Epson Connect registration has been improved so that it can be performed even when logged in to the operation panel with a sub-administrator account.
	Changes not related to security/ Vulnerabilities	other	other
09.68.WO24P9	Security Specification Change	Added the OAuth2 authentication support with Microsoft accounts for Email sending functions.	OAuth2 authentication with Microsoft accounts has been available for the following functions. - Scan / Storage / Fax to Email - Email Notification
09.67.WO29P8	Changes not related to security/ Vulnerabilities	other	other
09.67.WO24P7	Security Bug Fix	Under certain conditions, the embedded web browser sends requests using the HTTP protocol instead of HTTPS, even when HTTP is restricted.	The embedded web browser now sends requests using the HTTPS protocol as expected when HTTP is restricted.