

Firmware Update Information

Firmware Change History

Version	Category	Detail	Effect
06.98.XZ19P4	Security Bug Fix	Under certain conditions, the embedded web browser sends requests using the HTTP protocol instead of HTTPS, even when HTTP is restricted.	The embedded web browser now sends requests using the HTTPS protocol as expected when HTTP is restricted.